


PST-TIPS Technical Service Bulletin #2008-003

Release Date: April 18, 2008

Toll Free Number for Questions: (800) 762-6002 K-Tool International

Summary

TSB Topic:	Release of updated software (Version 1.3.4) for the KTI <i>p.s.t.</i> and TIPS tools.
Description of Issue:	<p>A new software revision, version 1.3.4, was released on April 11, 2008. This new software supersedes version 1.3.3 and includes support for the new sensor from TRW used on some models from Toyota, Acura and Honda, as well as verification for all known sensors on all other 2008 OEM vehicles.</p> <p>To trigger sensors in Manual Selection mode, users should select the same LED pattern that is used for all TRW sensors where LEDs #1 and #2 are illuminated before activating.</p>  <p>There have also been enhancements made to the tool performance.</p>
Vehicles Affected:	<p>Acura CSX (MY2008)</p> <p>Honda Civic (MY2008)</p> <p>Toyota Sequoia (MY2008)</p> <p>Toyota Sienna (MY2008)</p> <p>Toyota Tundra (MY2008)</p>

Current Software Version at time of TSB release	1.3.3
TPMS Sensors Affected:	TRW OEM part numbers: 42607-0C050 (Toyota) & 42753SNAA81 (Honda, Acura)
Summary:	A new software level has been released and is available to all PST and TIPS customers who own a Programming Interface Module (PIM) with a valid software license. Version 1.3.4 software replaces Version 1.3.3 and includes support for the new TRW sensor. This software release has been successfully verified on all other known sensors in 2008 MY vehicles.