

## TIPS Technical Service Bulletin #2006-002

Release Date: March 8, 2006

Toll Free Number for Questions: (800) 762-6002 K-Tool International

### Summary

TSB Topic:	<b>TIPS release of updated software (Version 1.2.9)</b>
Description of Issue:	<b>A new software level, Version 1.2.9, was released on August 30, 2005. The new software is required for your TIPS tool to work with the vehicles listed below.</b>
Vehicles Affected:	<b>Cadillac CTS (MY05-MY07) Cadillac SRX (MY04-MY06) Chevrolet TrailBlazer / EXT (MY06-MY08) GMC Envoy/XL/XUV (MY06-MY08) Buick Rainier (MY06-MY08)</b>
Current Software Version at time of TSB release	<b>1.3.1</b>
TPMS Sensors Affected:	<b>Schrader Bridgeport</b>
Summary:	<b>A new software level has been released and is available to all customers who have purchased a TIPS tool, own a Program Interface Module (PIM) with a valid software license. Version 1.2.9 software replaced Version 1.2.8, and is required for the TIPS tool to work with the vehicles listed above.</b>