

KTIp.s.t Technical Service Bulletin #2006-002

Release Date: March 8, 2006

Toll Free Number for Questions: (800) 762-6002 K-Tool International

Summary

TSB Topic:	KTIp.s.t release of updated software (Version 1.2.9)
Description of Issue:	A new software level, Version 1.2.9, was released on August 30, 2005. The new software is required for your KTIp.s.t tool to work with the vehicles listed below.
Vehicles Affected:	Cadillac CTS (MY05-MY07) Cadillac SRX (MY04-MY06) Chevrolet TrailBlazer / EXT (MY06-MY08) GMC Envoy/XL/XUV (MY06-MY08) Buick Rainier (MY06-MY08)
Current Software Version at time of TSB release	1.3.1
TPMS Sensors Affected:	Schrader Bridgeport
Summary:	A new software level has been released and is available to all customers who have purchased a KTIp.s.t tool, own a Program Interface Module (PIM) with a valid software license. Version 1.2.9 software replaced Version 1.2.8, and is required for the KTIp.s.t tool to work with the vehicles listed above.