

KTip.s.t Technical Service Bulletin #2006-007

Release Date: November 7, 2006

Toll Free Number for Questions: (800) 762-6002 K-Tool International

Summary

TSB Topic:	KTip.s.t release of updated software (Version 1.3.2)
Description of Issue:	A new software level, Version 1.3.2 was released on October 12, 2006. The new software includes improvements to the KTip.s.t Tool's "hunting feature" as well as its overall operation.
Vehicles Affected:	None
Current Software Version at time of TSB release	1.3.2
TPMS Sensors Affected:	None
Summary:	A new software level has been released and is available to all customers who have purchased a KTip.s.t and own a Programming Interface Module (PIM) with a valid software license. Version 1.3.2 software replaces Version 1.3.1 and includes improvements to the KTip.s.t's "hunting feature" as well as its overall operation. PIM software Version 2.0 is required to download tool software Version 1.3.2.

Body of TSB

Improvements to the Hunting Feature

Software modifications have been made to improve and speed up the hunting process of the KTip.s.t. In addition, hardware modifications have been made so when the KTip.s.t is "hunting" the 4 LEDs, at the top of the tool, scroll from left to right indicating that the tool is in the "hunt mode".

New Time Out Feature

A new Time Out Feature has been added to the KTip.s.t. Now, whenever the tool times out or is unable to trigger a sensor, the user is notified by two oscillating audible tones and all 4 LEDs blinking on and off twice.